SAMPLE NAME	SAMPLE LOCATION	DATE COLLECTED	RESULT	Qualifier	UNIT	REPORTING LIMIT
IR-9-1-K-KF-P-01	Faucet Located in Kitchen	12/20/2022	0.00095	J	mg/L	0.0020
IR-9-1-K-KF-F-01	Faucet Located in Kitchen	12/20/2022	0.0020	U	mg/L	0.0020
IR-9-1-K-KF-P-02	Faucet Located in Kitchen	12/20/2022	0.0029		mg/L	0.0020
IR-9-1-K-KF-F-02	Faucet Located in Kitchen	12/20/2022	0.00075	J	mg/L	0.0020
IR-9-1-K-KF-P-03	Faucet Located in Kitchen	12/20/2022	0.0035		mg/L	0.0020
IR-9-1-K-KF-F-04	Faucet Located in Kitchen	12/20/2022	0.0020	U	mg/L	0.0020
IR-9-1-K-KF-P-04	Faucet Located in Kitchen	12/20/2022	0.0068		mg/L	0.0020
IR-9-1-K-KF-F-04	Faucet Located in Kitchen	12/20/2022	0.0020	U	mg/L	0.0020
IR-9-1-CAF-WBF-P-5	Water Bottle Filler located in Cafeteria	12/20/2022	0.016		mg/L	0.0020
IR-9-1-CAF-WBF-S-5	Water Bottle Filler located in Cafeteria	12/20/2022	0.017		mg/L	0.0020
IR-9-1-CAF-WBF-F-5	Water Bottle Filler located in Cafeteria	12/20/2022	0.014		mg/L	0.0020
IR-9-1-B125-OF-P-06	Office Faucet Located in RM B125	12/20/2022	0.010		mg/L	0.0020
IR-9-1-B125-OF-F-06	Office Faucet Located in RM B125	12/20/2022	0.0019	J	mg/L	0.0020
IR-9-1-B100-LIBF-P-07	Library Facet Located in RM B100	12/20/2022	0.0016	J	mg/L	0.0020
IR-9-1-B100-LIBF-F-07	Library Facet Located in RM B100	12/20/2022	0.020		mg/L	0.0020
IR-9-1-MR-DWC-P-08	Water Fountain w/Cooler outside Mens Room	12/23/2022	0.00075		mg/L	0.0020

Immediate Remedial Response
NA
Shut off/disconnect outlet, Post "Not for Drinking/Cooking at outlet,Provide Filters at Problem Tap, Continous Daily/Weekly Flushing, Provide Bottle Water, Resample
Shut off/disconnect outlet, Post "Not for Drinking/Cooking at outlet,Provide Filters at Problem Tap, Continous Daily/Weekly Flushing, Provide Bottle Water, Resample
Shut off/disconnect outlet, Post "Not for Drinking/Cooking at outlet,Provide Filters at Problem Tap, Continous Daily/Weekly Flushing, Provide Bottle Water, Resample
Shut off/disconnect outlet, Post "Not for Drinking/Cooking at outlet,Provide Filters at Problem Tap, Continous Daily/Weekly Flushing, Provide Bottle Water, Resample
NA
NA
Shut off/disconnect outlet, Post "Not for Drinking/Cooking at outlet,Provide Filters at Problem Tap, Continous Daily/Weekly Flushing, Provide Bottle Water, Resample
NA

Long-Term Remedial Response
NA
Provide Filters, Repalce Problem Outlet, Replace Pipe, Reconfigure Plumbing, Resample
Provide Filters, Repalce Problem Outlet, Replace Pipe, Reconfigure Plumbing, Resample
Provide Filters, Repalce Problem Outlet, Replace Pipe, Reconfigure Plumbing, Resample
Follow Immediate Remedial Response and Resample. If High Levels Remain follow the Long-Term Remedial Response: Provide Filters, Repalce Problem Outlet, Replace Pipe, Reconfigure Plumbing, Resample
NA
NA
Follow Immediate Remedial Response and Resample. If High Levels Remain follow the Long-Term Remedial Response: Provide Filters, Repalce Problem Outlet, Replace Pipe, Reconfigure Plumbing, Resample
NA

					-	
IR-9-1-MR-DWC-SS-08	Water Fountain w/Cooler outside Mens Room	12/23/2022	0.0020		mg/L	0.0020
IR-9-1-MR-DWC-F-08	Water Fountain w/Cooler outside Mens Room	12/23/2022	0.0020		mg/L	0.0020
IR-9-1-MR-DWC-P-09	Water Fountain w/Cooler outside Mens Room	12/23/2022	0.0020	U	mg/L	0.0020
IR-9-1-MR-DWC-SS-9	Water Fountain w/Cooler outside Mens Room	12/23/2022	0.030		mg/L	0.0020
IR-9-1-MR-DWC-F-9	Water Fountain w/Cooler outside Mens Room	12/23/2022	0.0020	U	mg/L	0.0020
IR-9-1-TL-LF-P-10	Lounge Faucet inside Teachers Lounge	12/23/2022	0.0050		mg/L	0.0020
IR-9-1-TL-LF-F-10	Lounge Faucet inside Teachers Lounge	12/23/2022	0.0012	J	mg/L	0.0020
IR-9-1-MR-DWC-P-11	Water Fountain w/Cooler outside Mens Room	12/23/2022	0.0020	U	mg/L	0.0020
IR-9-1-MR-DWC-SS-11	Water Fountain w/Cooler outside Mens Room	12/23/2022	0.0020	U	mg/L	0.0020
IR-9-1-MR-DWC-F-11	Water Fountain w/Cooler outside Mens Room	12/23/2022	0.0020	U	mg/L	0.0020
IR-9-1-WR-DWC-P-12	Water Fountain w/Cooler outside Womens Room	12/23/2022	0.0020	U	mg/L	0.0020
IR-9-1-WR-DWC-SS-12	Water Fountain w/Cooler outside Womens Room	12/23/2022	0.0020	U	mg/L	0.0020
IR-9-1-WR-DWC-F-12	Water Fountain w/Cooler outside Womens Room	12/23/2022	0.0020	U	mg/L	0.0020
IR-9-1-MR-DWC-P-13	Water Fountain w/Cooler outside Mens Room	12/23/2022	0.0020	U	mg/L	0.0020
IR-9-1-MR-DWC-SS-13	Water Fountain w/Cooler outside Mens Room	12/23/2022	0.0020	U	mg/L	0.0020
IR-9-1-MR-DWC-F-13	Water Fountain w/Cooler outside Mens Room	12/23/2022	0.0020	U	mg/L	0.0020
IR-9-1-MR-DWC-P-14	Water Fountain w/Cooler outside Mens Room	12/23/2022	0.0020	U	mg/L	0.0020

NA
NA
NA
Shut off/disconnect outlet, Post "Not for Drinking/Cooking at outlet,Provide Filters at Problem Tap, Continous Daily/Weekly Flushing, Provide Bottle Water, Resample
NA

NA
NA
NA
Follow Immediate Remedial Response and Resample. If High Levels Remain follow the Long-Term Remedial Response: Provide Filters, Repalce Problem Outlet, Replace Pipe, Reconfigure Plumbing, Resample
NA

IR-9-1-MR-DWC-SS-14	Water Fountain w/Cooler outside Mens Room	12/23/2022	0.0020	U	mg/L	0.0020
IR-9-1-MR-DWC-F-14	Water Fountain w/Cooler outside Mens Room	12/23/2022	0.0020	U	mg/L	0.0020
IR-9-1-MR-DWC-P-15	Water Fountain w/Cooler outside Mens Room	12/23/2022	0.00083	J	mg/L	0.0020
IR-9-1-MR-DWC-SS-15	Water Fountain w/Cooler outside Mens Room	12/23/2022	0.0020	U	mg/L	0.0020
IR-9-1-MR-DWC-F-15	Water Fountain w/Cooler outside Mens Room	12/23/2022	0.0020	U	mg/L	0.0020

K	ey - Sample Name
Р	Primary Sample
SS	Sequential Sample
F	Flush Sample

	Key - Qualifier
U	Not Detected in Laboratory Analysis
J	Result is Between Laboratory Detection Limit & Laboratory Reporting Limit

NA
NA
NA
NA
NA

NA
NA
NA
NA
NA